

Personal Scale

Specifications

- ★ Starting Weight :5kg/11lb
- ★ Capacity : 180kg
- ★ Graduation :50g/0.2lb
- ★ Display :4 digits LCD
- ★ Power :2x1.5V (AAA) / CR2032 lithium battery
- ★ Operating temperature :5-35 degrees Celsius
- ★ Unit : kg / lb
- ★ Automatic shutdown :10 seconds
- ★ Low voltage display : "Lo"
- ★ Overweight display : "oL"

Instructions

- ★ Put the scale on the level of the ground, after the scale shows 0.00kg, you can step on the scale.
- ★ Stand steady in the middle of the scale. When the weight value is stable, the weight value is locked.
- ★ If you leave the scale and step on the scale again after locked, you can reweigh.
- ★ If you don't leave scale after locked, the value remained 10 seconds before the automatic shutdown
- ★ If the scale displays "Lo", the battery is inefficient and should be replaced.

Attention

- ★ When not using the scale, don't put heavy objects on the scale for a long time.
- ★ When weighing, you should try to stand in the middle of the scale.
- ★ You should stand steady on the scale.
- ★ The scale can't be hit hard.
- ★ Do not use the scale where there is water. don't wash the scale with water.
- ★ Battery has been installed in the scale in the factory.
- ★ Maintain the scale and your feet drying when weighing.

