


Product iron connector



1. Insert into the small hole



2. Drill tight nut



(firm)

Four steps to avoid punching

four steps



(step1)

Remove dust and oil
stains from the wall



(step2)

Tear off the scratch free
protective film



(step3)

Stick to the wall and
squeeze out the air



(step4)

Installation completed
by buttoning down